



Clean Room Certification and Balance Report

PM Tool
315 North Park Drive
San Antonio, Tx 78216

FED-STD-209E/ISO 14644

Airflow Analysis

Room Name/# Ante

HEPA Filters

Yes No HEPA filters located in duct system.

Yes No HEPA filters scanned/probed for leaks.

Yes No Leaks detected.

Yes No Leaks Repairable.

Yes No Leaks Repaired.

Ceiling HEPA Filter Sizes

HEPA Filter Sizes: 22"x44"

1 thru 1 = 7 Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

Air Flows

Total Ceiling HEPA Filters CFM = 630

Hood CFM (If Required) = N/A

Remarks- _____

Airflow Analysis

Room Name/# Clean Room

HEPA Filters

Yes No HEPA filters located in duct system.

Yes No HEPA filters scanned/probed for leaks.

Yes No Leaks detected.

Yes No Leaks Repairable.

Yes No Leaks Repaired.

Ceiling HEPA Filter Sizes

HEPA Filter Sizes: 22"x46" _____

1 thru 5 = 35 Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

_____ thru _____ = _____ Sq. Ft.

Air Flows

Total Ceiling HEPA Filters CFM= _____ 3,114 _____

Hood CFM (If Required)= _____

Remarks- _____

Remarks/Recommendations- At the time of testing the rooms were observed holding temperature at 65 degrees Fahrenheit, and maintaining a relative humidity level between 44%-47% RH.